







11PCS GARAGE TOOL CABINET













	PART	QUANTITY
1.	 $\varnothing 8$	4
2.	 M6X30	4
3.		1
4.		1
5.		4
6.		4
7.	 M6X12	8







PART		QUANTITY
1.	 Ø8	4
2.	 M6X30	4
3.		1
4.		1







PART			QUANTITY
1.	 $\varnothing 8$		4
2.	 M6X30		4










PART		QUANTITY
1.	 $\varnothing 8$	4
2.	 M6X30	4
3.		1
4.		1
5.		4
6.		4
7.	 M6X12	8





	PART	QUANTITY
1.	 $\varnothing 8$	4
2.	 M6X30	4
3.		5
4.		4
5.		4
6.	 M6X12	8





	PART	QUANTITY
1.		6
2.		2
3.		2
4.	 M8X12	16